

Facility
 Environmental Protection Licence Number
 Link to Licence (EPA Website)
 Licencee
 Licencee's address

Bermagui Recycling & Waste Depot
 6047
<http://www.environment.nsw.gov.au/prpoeoapp/SearchResult.aspx?SearchTag=licence&searchchange=licence&range=licence>
 Bega Valley Shire Council
 Zingel Place (PO Box 492) Bega NSW 2550

EPA monitoring point	Description 1	Description 2	pollutant	unit	no of samples required	no of samples collected	lowest	Mean	highest	Date Sampled			
										13-November-2014	18-February-2015	14-May-2015	18-August-2015
3	Leachate Dam South	L1	Ammonia	mg/L	4	4	3.6	5.7	10.1	3.7	3.6	10.1	5.4
3	Leachate Dam South	L1	BOD	mg/L	4	4	3.0	6.8	8.0	8	8	3	8
3	Leachate Dam South	L1	Conductivity	siemens	4	4	609.0	709.9	821.4	609	750	821.4	659
3	Leachate Dam South	L1	pH	pH	4	4	7.3	8.0	8.7	8.7	8.5	7.3	7.63
3	Leachate Dam South	L1	Total suspended solids	mg/L	4	4	4.0	14.3	21.0	20	21	4	12
4	Sediment Dam	S1	Ammonia	mg/L	4	4	0.0	0.0	0.0	0.01	0	0	0
4	Sediment Dam	S1	BOD	mg/L	4	4	6.0	12.8	31.0	31	7	6	7
4	Sediment Dam	S1	Conductivity	siemens	4	4	395.0	679.3	946.0	946	440	936	395
4	Sediment Dam	S1	pH	pH	4	4	7.1	8.2	10.4	10.4	8.1	7.1	7.36
4	Sediment Dam	S1	Total suspended solids	mg/L	4	4	52.0	112.5	180.0	108	110	52	180
6	Leachate Dam North	L2	Ammonia	mg/L	4	4	0.0	0.1	0.2	0.2	0	0.2	0.1
6	Leachate Dam North	L2	BOD	mg/L	4	4	2.0	4.0	8.0	3	3	2	8
6	Leachate Dam North	L2	Conductivity	siemens	4	4	160.0	194.0	210.0	201	210	205	160
6	Leachate Dam North	L2	pH	pH	4	4	7.0	7.3	7.5	7.3	7.5	7	7.24
6	Leachate Dam North	L2	Total suspended solids	mg/L	4	4	6.0	9.0	17.0	6	6	7	17