
9 FLOOD PHOTOS

Flood photos taken during the February 1971, March 2011, and February 2010 events are presented below. The photos shown are not necessarily during the peak of the flood and peak levels may be higher. Photos have been sourced from Council's flood library or obtained during the course of the study.

9.1 February 1971 Event



9.2 March 2011 Event

Candelo Creek Bridge



(source: Jack Canavan)

Downstream of Candelo Creek Bridge



(source: Jack Canavan)

Carp Street – Bega (when flooded)



(source: Jack Canavan)



Yallumba Creek Bridge

(source: Jack Canavan)


Carp Street - Bega



(source: Jack Canavan) Carp Street – Bega (when dry)



(source: GoogleEarth)





(source: BVSC)

Tarraganda Lane



(source: BVSC)

Debris at Tarraganda Lane bridge



(source: BVSC) Flood Damage at Tarraganda Lane bridge



(source: BVSC)

Floodwaters



(source: BVSC)



(source: BVSC)



(source: BVSC)

9.3 February 2010 Event

